


สเก็ทกลมจัน


| | | | | | | | | | |
|--------------|------|-----|------|-----|-----|-----|-----|-----|----|
| d (Diameter) | 3/16 | 1/4 | 5/16 | 3/8 | 1/2 | 5/8 | 3/4 | 7/8 | 1 |
| d2 | 5 | 6 | 8 | 10 | 12 | 15 | 19 | 21 | 23 |
| b | 7 | 8 | 11 | 14 | 17 | 21 | 27 | 30 | 33 |
| h | 15.5 | 18 | 24 | 30 | 36 | 49 | 61 | 67 | 73 |



| Size | 3/16 | 1/4 | 5/16 | 3/8 | 1/2 | 5/8 | 3/4 | 7/8 | 1 | 1.1/4 | 1.1/2 |
|-------------|------|-----|------|-----|-----|-----|-----|-----|----|-------|-------|
| สเก็ท สีเงา | 100 | 100 | 50 | 50 | 50 | 15 | 10 | 10 | 10 | 10 | 10 |

คลิปสลิง


| | | | | | | | | | |
|--------------|-----|------|-----|------|-----|-----|-----|-----|----|
| d (Diameter) | 1/8 | 3/16 | 1/4 | 5/16 | 3/8 | 1/2 | 5/8 | 3/4 | 1 |
| a | 9 | 11 | 13 | 16 | 19 | 24 | 29 | 37 | 41 |
| h1 | 20 | 24 | 28 | 34 | 42 | 55 | 63 | 85 | 95 |
| L | 21 | 23 | 26 | 30 | 34 | 42 | 50 | 61 | 65 |
| t | 10 | 11 | 12 | 14 | 18 | 23 | 26 | 33 | 35 |



| Size | 1/8 | 3/16 | 1/4 | 5/16 | 3/8 | 1/2 | 5/8 | 3/4 | 7/8 | 1 | 1.1/4 |
|----------------------|-----|------|-----|------|-----|-----|-----|-----|-----|----|-------|
| คลิปสลิง-เหล็กหล่อ | 100 | 100 | 100 | 100 | 50 | 50 | 25 | 25 | 50 | 50 | |
| คลิปสลิง-เหล็กเหนียว | 100 | 100 | 100 | 100 | 50 | 50 | 25 | 25 | 50 | 50 | |

ห่วงหัวใจ


| | | | | | | | | | | |
|----|-----|------|-----|------|-----|-----|-----|-----|-----|---|
| a | 1/8 | 3/16 | 1/4 | 5/16 | 3/8 | 1/2 | 5/8 | 3/4 | 7/8 | 1 |
| b | 19 | 22 | 29 | 38 | 44 | 57 | | | | |
| c | 11 | 16 | 19 | 24 | 32 | 38 | | | | |
| L | 25 | 31 | 37 | 51 | 64 | 76 | | | | |
| L1 | 16 | 22 | 26 | 34 | 42 | 51 | | | | |



| Size | 1/8 | 3/16 | 1/4 | 5/16 | 3/8 | 1/2 | 5/8 | 3/4 | 7/8 | 1 |
|--------------|-----|------|-----|------|-----|-----|-----|-----|-----|----|
| ห่วงหัวใจบาง | | | 200 | 200 | 25 | 25 | 20 | 20 | 50 | 50 |
| ห่วงหัวใจหนา | | | | | 25 | 25 | 20 | 20 | 50 | 50 |

เกลียวเร่งแบน

| | | | | | | | | |
|----|-----|------|-----|------|-----|-----|-----|-----|
| d1 | 1/8 | 3/16 | 1/4 | 5/16 | 3/8 | 1/2 | 5/8 | 3/4 |
| L1 | | 73 | 110 | 110 | 125 | 125 | 170 | 200 |
| L1 | | 122 | 166 | 177 | 208 | 227 | 305 | 353 |



| Size | 1/8 | 3/16 | 1/4 | 5/16 | 3/8 | 1/2 | 5/8 | 3/4 | 7/8 | 1 |
|-----------------------------|-----|------|-----|------|-----|-----|-----|-----|-----|----|
| เกลียวเร่งแบน กระบอกใหญ่ | 100 | 50 | 50 | 30 | 25 | 20 | 20 | 20 | 50 | 50 |
| เกลียวเร่งแบน กระบอกเล็ก | | | | | | 20 | 20 | 20 | | |